

960, 1995, B6304FS2, AW30-40, L.H.D

6/5/2014




**PRINT**

## Replacing front fender

### Remove:

- headlamp.
- turn signal lamp.
- screws holding fender. 6 on top. 2 at the rear edge (A-pillar side). 1 at lower edge (see illustration).



### Install:

In reverse order.

Apply rustproofing agent to flanges, wheel arch and fenders

6/5/2014

**PRINT**